

Address: 9264 SVL Box

Victorville, CA 92395

Report Date: 09-Sep-2014

Analytical Report: Page 1 of 6
Project Name: No Project
Project Number: Calico Rd

Work Order Number: B4H2595

Received on Ice (Y/N): Yes Temp: 8 °C

Attached is the analytical report for the sample(s) received for your project. Below is a list of the individual sample descriptions with the corresponding laboratory number(s). Also, enclosed is a copy of the Chain of Custody document (if received with your sample(s)). Please note any unused portion of the sample(s) may be responsibly discarded after 30 days from the above report date, unless you have requested otherwise.

Thank you for the opportunity to serve your analytical needs. If you have any questions or concerns regarding this report please contact our client service department.

Sample Identification

Lab Sample #	Client Sample ID	<u>Matrix</u>	Date Sampled	$\underline{\mathbf{B}}\mathbf{y}$	Date Submitte	<u>d</u> <u>By</u>
B4H2595-01	Sample #1	Solid	08/25/14 14:00	Paul Beoger	08/26/14 12:42	Paul Beoger
B4H2595-02	Sample #2	Solid	08/25/14 14:00	Paul Beoger	08/26/14 12:42	Paul Beoger
B4H2595-03	Sample #3	Solid	08/25/14 14:00	Paul Beoger	08/26/14 12:42	Paul Beoger
B4H2595-04	Sample #4	Solid	08/25/14 14:00	Paul Beoger	08/26/14 12:42	Paul Beoger



Address: 9264 SVL Box

Report Date: 09-Sep-2014

Victorville, CA 92395

Victorville, CA 9239

Analytical Report: Page 2 of 6
Project Name: No Project
Project Number: Calico Rd

Work Order Number: B4H2595

Received on Ice (Y/N): Yes Temp: 8 °C

Laboratory Reference Number

B4H2595-01

Sample DescriptionMatrixSampled Date/TimeReceived Date/TimeSample #1Solid08/25/14 14:0008/26/14 12:42

Analyte(s)	Result	RDL	Units	Method	Analysis Date Ana	alyst Flag
Diesel Range Organics by EPA 8015 Diesel Range Hydrocarbons	ND	10	mg/kg	EPA 8015E	3 09/05/14 18:35	jhr
Surrogate: Decachlorobiphenyl	89.4	% 35-138		EPA 8015	3 09/05/14 18:35	jhr



Address: 9264 SVL Box

Report Date: 09-Sep-2014

Victorville, CA 92395

Analytical Report: Page 3 of 6 Project Name: No Project Project Number: Calico Rd

Work Order Number: B4H2595

Received on Ice (Y/N): Yes Temp: 8 °C

Laboratory Reference Number

B4H2595-02

Sample Description Sampled Date/Time Received Date/Time Matrix Sample #2 Solid 08/25/14 14:00 08/26/14 12:42

Analyte(s)	Result	RDL	Units	Method	Analysis Date Ana	alyst Flag
Gasoline Range Organics by EPA 8015						
Gasoline Range Organics	ND	5.0	mg/kg	EPA 8015B	09/03/14 21:13	jes
Surrogate: a,a,a-Trifluorotoluene	23.8	% 16-130		EPA 8015E	09/03/14 21:13	jes



Address: 9264 SVL Box

Victorville, CA 92395

Victorville, CA 9239

Report Date: 09-Sep-2014

Analytical Report: Page 4 of 6
Project Name: No Project
Project Number: Calico Rd

Work Order Number: B4H2595

Received on Ice (Y/N): Yes Temp: 8 °C

Laboratory Reference Number

B4H2595-03

Sample DescriptionMatrixSampled Date/TimeReceived Date/TimeSample #3Solid08/25/14 14:0008/26/14 12:42

Analyte(s)	Result	RDL	Units	Method	Analysis Date Ana	alyst Flag
Diesel Range Organics by EPA 8015 Diesel Range Hydrocarbons	ND	10	mg/kg	EPA 8015B	3 09/05/14 17:45	jhr
Surrogate: Decachlorobiphenyl	86.8	% 35-138		EPA 8015E	3 09/05/14 17:45	jhr



Address: 9264 SVL Box

Report Date: 09-Sep-2014

Victorville, CA 92395

VICTORVINE, CA 92390

Analytical Report: Page 5 of 6
Project Name: No Project
Project Number: Calico Rd

Work Order Number: B4H2595

Received on Ice (Y/N): Yes Temp: 8 °C

Laboratory Reference Number

B4H2595-04

Sample DescriptionMatrixSampled Date/TimeReceived Date/TimeSample #4Solid08/25/14 14:0008/26/14 12:42

Analyte(s)	Result	RDL	Units	Method	Analysis Date A	nalyst	Flag
Gasoline Range Organics by EPA 8015							
Gasoline Range Organics	ND	5.0	mg/kg	EPA 8015E	3 09/03/14 21:51	1 jes	
Surrogate: a.a.a-Trifluorotoluene	24.3	% 16-130		EPA 8015E	3 09/03/14 21:51	l jes	



Address: 9264 SVL Box

Victorville, CA 92395

Report Date: 09-Sep-2014

Analytical Report: Page 6 of 6
Project Name: No Project
Project Number: Calico Rd

Work Order Number: B4H2595

Received on Ice (Y/N): Yes Temp: 8 °C

Notes and Definitions

ND: Analyte NOT DETECTED at or above the Method Detection Limit (if MDL is reported), otherwise at or

above the Reportable Detection Limit (RDL)

NR: Not Reported

RDL: Reportable Detection Limit
MDL: Method Detection Limit

* / "": NELAP does not offer accreditation for this analyte/method/matrix combination

Approval

Enclosed are the analytical results for the submitted sample(s). Babcock Laboratories certify the data presented as part of this report meet the minimum quality standards in the referenced analytical methods. Any exceptions have been noted. Babcock Laboratories and its officers and employees assume no responsibility and make no warranty, express or implied, for uses or interpretations made by any recipients, intended or unintended, of this report.

cc:



Address: 9264 SVL Box

Report Date: 09-Sep-2014

Victorville, CA 92395

Analytical Report: Page 1 of 1 Project Name: No Project Project Number: Calico Rd

Work Order Number: B4H2595

Received on Ice (Y/N): Yes Temp: 8 °C

E.S. Babcock & Sons, Inc.
6100 Quail Valley Ct., Riverside, CA 92507
(951) 653-3351 Project Reference
County Design Francisco
Client Paul Benner + Agar, aton
Submitted By: Paul Borsor DA \$240 UB
Date: 8/26/14 COSH 8.26.194
Time: 1242
Submitted By: Paul Borner Date: 8/26/14 Time: 1242 Sample Condition Number of Containers: 4
Number of Containers:
Temperature:
Were Samples Submitted on Ice? No Yes
Were Samples Received Intact? No (Yes)
Were Samples in Proper Containers? No Yes
Were Sample Custody Seals Intact? No Yes N/A
Chain of Custody Received? No Yes
Submitted within Reg. Holding Times? No (Yes)
Is there Sufficient Volume? No (Yes)
Proper Travel Blank/Field Blank(s) Submitted? No Yes N/A
Comments: 1) Calico Rd # 1 8/25/14 2pm 805 D - 2) Calico Rd #2 " by Paul
8015D - 3) (alico 'Kd #3 " " believ
80156 Sample(s) Received By: 4 Staff
Problem Contact Information: Person Contacted: Date/Init.: Permission to Continue? Yes No