HYDRANT FLOW TEST REPORT



Physical Address: 855 West Base Line, Rialto, CA 92376 Phone: (909) 875-1804, Fax: (909) 875-1849

Date February 23, 2021		
APPLICANT Joseph E. Bonadiman & Associates, Inc.		
Address 234 N. Arrowhead Avenue		
City/State San Bernardino, CA	Zip Code	e <u>92408</u>
Phone No. <u>(909) 885-3806</u> F	ax No Email <u>vbrady@bonadim</u>	nan.com
FLOW TEST REQUIRED FOR: (PLEASE COMPLETE ONE OR MORE) Address18720 Wrangler Dr., Bloomington, CA Assessor's Parcel No		
Tract/Lot Locati	on	
SUBMIT TEST RESULT: ☐ MAIL ☐ FAX ✓ EMAIL ☐ PICK-UP ***********************************		
FEE SCHEDULE		
A non-refundable charge in the amount of		
\$150.00 will be charged for each flow test performed. ************************************		
DISTRICT USE ONLY		
TEST DATE <u>2/11/21</u>	TIME 9:00:	a m
GENERAL LOCATION _Flow hydrant located southeast corner of Cedar Ave. & Wrangler Dr.		
Gauge hydrant located west side of Cedar 60' south of Wrangler		
MAIN SIZE/TYPE <u>12" PVC</u> PRESS		
HYDRANT NO. H-23 HYDRANT TYPE Clow 850 HYDRANT SIZE 6"		
		HYDRANT
	100	98
	95	95
	75 21/1 OUTLET C Forton	-f 00
CALCULATED WATER LOSS	<u>1292</u> 2½" OUTLET, C Factor 1455 GALLONS	01.00
CALCOLATED WATER LOSS 1433 GALLONS		

This is a non-certified fire flow test. Test results indicate the capability of the water system at the time the test was taken. Since the capacity of the water system may vary as a result of many factors, including demand placed on the system by the District's customers, we recommend that you give adequate consideration to these variations when performing your analysis.

Sincerely,

Linda Jadeski
Engineering Services Manager

WEST VALLEY WATER DISTRICT

a Jadeshi