

BNS Route Report

H6170 - Ann Irick

For Service Date: 8/26/2020

Ann Irick

Route #	Permit #	Street #	Street Name	City/Area	Inspection Type	Service Code	Start Time	End Time	Start Odometer	End Odometer	Results
1	SFR-2019-00179	13640	SIERRA VISTA DR	Victorville	Sewer Lateral	Permit Inspection					
2	SFR-2018-00334	36030	SAGE ST	Lucerne Valley	Final	Permit Inspection					
3	ELEC-2020-00725	9122	SAN JACINTO ST	Morongo Valley	Final	Permit Inspection					
4	SFR-2019-00805	9625	BELLA VISTA ST	Morongo Valley	Combo	Permit Inspection					
5	ACCR-2019-00920	9625	BELLA VISTA RD	Morongo Valley	Combo	Permit Inspection					
6	SFR-2020-00091	5256	WILLIAMS S HART RD	Pioneer Town	Combo	Permit Inspection					
7	SFR-2019-00814	53265	ANNIE OAKLEY RD	Pioneer Town	SetBacks, Reinforcing steel, excavations and forms	Permit Inspection					
8	ACCR-2019-00807	57735	LUNA VISTA LN	Yucca Mesa	Lath or drywall nailing	Permit Inspection					
9	MFGH-2020-00025	415	INCA TRL	Yucca Valley	Septic Tank and Pit or Line	Permit Inspection					

BNS Route Report

G3547 - Jim Miller

For Service Date: 8/26/2020

Jim Miller

Route #	Permit #	Street #	Street Name	City/Area	Inspection Type	Service Code	Start Time	End Time	Start Odometer	End Odometer	Results
1	ALTR 2020 00534	14600	BRYMAN RD.	Oro Grande	Other (fill out the notes field w/detail)	Permit Inspection					
2	SFR 2019 00836	27346	PENINSULA LN.	Silver Lakes	Combo	Permit Inspection					
3	SOLAR 2020 00158	35754	FRONTIER AVE.	Yermo	Electrical	Permit Inspection					
4	SOLARNR 2019 00027	43761	TERRIER TRAIL	Yermo	Electrical	Permit Inspection					
5	ACCR 2017 00333	33938	j ST.	Barstow	Other (fill out the notes field w/detail)	Permit Inspection					
6	ALTR 2020 00658	24660	CAHUIILLA RD.	Apple Valley	Electrical	Permit Inspection					
7	ACCR 2019 00813	11930	MANZANA DR	Apple Valley	Final	Permit Inspection					
8	POOL 2020 00113	26175	RANCHO ST.	Apple Valley	Pool Deck Bond	Permit Inspection					
9	SFR 2020 00227	9230	SAGEBRUSH ST	Apple Valley	Ground Plumbing	Permit Inspection					