

BNS Route Report

H6170 - Ann Irick

For Service Date: 8/26/2020

Ann Irick

Route #	Permit #	Street #	Street Name	City/Area	Inspection Type	Service Code	Start Time	End Time	Start Odometer	End Odometer	Results
1	SFR-2019-00179	13640	SIERRA VISTA DR	Victorville	Sewer Lateral	Permit Inspection					
2	SFR-2018-00334	36030	SAGE ST	Lucerne Valley	Final	Permit Inspection					
3	ELEC-2020-00725	9122	SAN JACINTO ST	Morongo Valley	Final	Permit Inspection					
4	SFR-2019-00805	9625	BELLA VISTA ST	Morongo Valley	Combo	Permit Inspection					
5	ACCR-2019-00920	9625	BELLA VISTA RD	Morongo Valley	Combo	Permit Inspection					
6	SFR-2020-00091	5256	WILLIAMS S HART RD	Pioneer Town	Combo	Permit Inspection					
7	SFR-2019-00814	53265	ANNIE OAKLEY RD	Pioneer Town	SetBacks, Reinforcing steel, excavations and forms	Permit Inspection					
8	ACCR-2019-00807	57735	LUNA VISTA LN	Yucca Mesa	Lath or drywall nailing	Permit Inspection					
9	MFGH-2020-00025	415	INCA TRL	Yucca Valley	Septic Tank and Pit or Line	Permit Inspection					